

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

AMENDMENTS TO THE SPECIFICATION

On page 1, before "FIELD OF THE INVENTION," please insert the following:

—The present application is a national stage under 35 U.S.C. § 371 of PCT/CA99/00638, filed July 15, 1999, which is a continuation-in-part of U.S. Patent Application Serial No. 09/116,732, now issued U.S. Patent No. 6,017,504.—

Please replace the paragraph on page 3, lines 4-13, with the following amended paragraph:

—The most common method for preparing perovskite and perovskite-like catalysts is the traditional method called "ceramic". This method simply consists in mixing constituent powders (oxides, hydroxides or carbonates) and sintering the powder mixture thus formed to high temperature. The problem with this method is that calcination at high temperature (generally above 1000°C) is necessary to obtain the crystalline perovskite or perovskite-like crystalline structure. Another drawback is that low specific surface area value is obtained (SS around 1 m²/g). An example of such a high temperature heating method is disclosed in U.S. Patent No. 5,093,301 where a perovskite structure to be used in a catalyst is formed after heating a ground dry powder mixture at 1300°C.—